



CF

I hereby certify that this correspondence
is being deposited with the United States
Postal Service as first class mail in an
envelope addressed to:
Commissioner for Patents
United States Patent & Trademark Office
Attention: Certificate of Correction Branch
P.O. Box 1450
Alexandria, VA 22313-1450, on 5/23/05
Barbara Mirianni
DATE May 23, 2005

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Examiner: Jason S. Morrow :
Group Art Unit: 3612 :
In re application of :
Dinesh C. Seksaria et al. : FRONT END APRON ASSEMBLY
: FOR A MOTOR VEHICLE
Serial No. 10/816,501 :
Filed: April 1, 2004 :
Patent No. 6,886,886 B2 :
Issued: May 3, 2005 :
ATTORNEY DOCKET: 370050-00002-5

Certificate
MAY 31 2005
of Correction

L E T T E R

600 Grant St., 44th Floor
Pittsburgh, PA 15219
May 23, 2005

Commissioner for Patents
United States Patent & Trademark Office
Attention: Certificate of Correction Branch
P.O. Box 1450
Alexandria, VA 22313-1450

Sir:

In comparing the above-identified original patent document with the original papers filed in the Patent and Trademark Office, we have noted ten (10) errors which were the printer's errors.

JUN 01 2005

It is respectfully requested that a Certificate of Correction be issued to correct these printing errors in the above-identified patent.

Respectfully submitted,



Grant E. Coffield
Registration No. 52,758
Attorney for Applicant

(412) 566-6965

JUN 01 2005

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,886,886 *B2*

DATED : May 3, 2005

INVENTOR(S) : Dinesh C. Seksaria et al.

It is certified that errors appear in the above-identified patent and that said Letters Patent should be corrected as shown below:

Col. 3, line 64, insert --,-- after "members".

Col. 6, line 23, "owing" should read --the following--.

Col. 6, line 24, insert --parts are-- after "like".

Col. 9, line 53, insert --side 118-- after "first".

Col. 11, line 45, insert --the-- after "by".

Col. 11, line 52, delete "(not yet assigned)", insert --(10/271,449)--.

Col. 12, line 58, "304,306" should read --304, 306--.

Col. 15, line 59, "gassembly" should read --assembly--.

Col. 15, lines 61 & 64, "200-100" should, in both instances, read --200-400--.

1 of 1

MAILING ADDRESS OF SENDER:

Sally Novosel, Docket Administrator
ECKERT SEAMANS CHERIN & MELLOTT, LLC
600 Grant Street, 44th Floor
Pittsburgh, PA 15219

PATENT NO. 6,886,886 *B2*


No. of add'l. copies

@ 50¢ per page


⇒

JUN 01 2005

ECKER
SEAMANS



United States Patent & Trademark Office
Certificate of Correction Branch
Mail Stop: Certificate of Correction
P.O. Box 1450
Alexandria, VA 22313-1450



22313-1450